

RESOLUTION NO. 17-050

A RESOLUTION OF THE CITY COUNCIL OF THE CITY OF PASO ROBLES  
AUTHORIZING THE REMOVAL OF ONE 38" VALLEY OAK TREE  
AT 515 21<sup>ST</sup> STREET  
(OTR 17-005 / LINDA THORNDYKE) APN: 008-221-006

WHEREAS, Linda Thorndyke has filed a request for the removal of one 38" Valley oak tree located adjacent to the house located at 515 21<sup>st</sup> Street; and

WHEREAS, an Arborist Report prepared by Rodney Thurman, Certified Arborist has been provided which concludes that the tree has structural issues that make it prone to failure; and

WHEREAS, the Community Development Director could not make the determination that the tree is "clearly dead or diseased beyond correction," and therefore, Section 10.01.050.C of the Oak Tree Ordinance would consider the tree "healthy" and require that the City Council make the determination of whether the tree should be removed or not, after consideration of the factors listed in Section 10.01.050.D; and

NOW, THEREFORE, THE CITY COUNCIL OF THE CITY OF EL PASO DE ROBLES DOES HEREBY RESOLVE AS FOLLOWS:

Section 1. All of the above recitals are true and correct and incorporated herein by reference.

Section 2. Findings: Pursuant to Paso Robles Municipal Code section 10.01.050.D., and based on the entire record including all written and oral evidence presented, the City Council finds as follows:

1. Having considered the factors outlined in Section 10.01.050.D.1. of the Paso Robles Municipal Code, and the information provided by the Arborist in Exhibit A, the City Council finds that allowing the removal of the tree would seem to be consistent with finding D.1, based on the trees being in poor condition, and allowing for the removal of the tree would prevent the possibility of the tree falling into the fairway where golfers and golf course employees are present throughout the day. Mitigation trees/fees will be required.

Section 3: Approval. The City Council of the City of El Paso de Robles does hereby:

1. Authorize the removal of one 38" Valley Oak tree located adjacent to the house at 515 21<sup>st</sup> Street, based on the trees being in poor health and prone to failure, as indicated in the Arborist Report, attached as Exhibit A;
2. Require one (1) 1.5-inch diameter Live Oak replacement tree on site and payment into the City's replacement fund for the remaining (5) replacement trees.

APPROVED this 18th day of April, 2017, by the following vote:

AYES: Strong, Hamon, Gregory, Reed, Martin

NOES:

ABSENT:

ABSTAIN:

  
\_\_\_\_\_  
Steven W. Martin, Mayor

ATTEST:

  
\_\_\_\_\_  
Kristen L. Buxkemper, Deputy City Clerk

Exhibit A: Arborist Report



P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

RECEIVED  
MAR 13 2017  
City of Paso Robles  
Community Development Dept.

March 10, 2017

**Re:** Tree Risk Assessment for Linda Thorndyke 515 21<sup>st</sup> Street in Paso Robles, CA

**To:** Darin Nash- City of Paso Robles Community Development Director

**From:** Rodney Thurman- Whit's Turn Tree Care

Dear Mr. Nash,

This letter is to inform you of the current tree health and structural stability of one (1) Valley Oak (*Quercus lobata*) located on the east side of 515 21<sup>st</sup> street. I visited the property on February 13, 2017 and did a ground based inspection of the tree and found the following:

**Observations:**

- The tree is a single stem measuring 38 inches in diameter at breast height (DBH), measured at 4.5 feet above ground level. The tree height is approximately 50 feet tall with a crown spread of approximately 40 feet. **See Appendix A- Photo1**
- The critical root zone (CRZ) has had been covered approximately 50% by a cement driveway and parking area. Another 30% of the CRZ is covered by the footprint of the house. Open yard area for root growth is approximately 20%. **See Appendix A- Photos2&3**
- The tree is located 5.5 feet east of the foundation of the house and the root crown is making contact with the cement parking pad of the carport. **See Appendix A- Photos 3**
- The root crow has been buried below grade at least 12 inches. **See Appendix A- Photos 3**
- A large branch has been removed from the lower trunk of the tree on the north side. The wound created by the cut is approximately 18 inches X 24 inches and is showing signs of decay. **See Appendix A- Photo 4**
- The tree has a 30 degree lean west toward the home. **See Appendix A- Photos 1&4**
- The tree has been topped in the past and no lateral branches are left. Only epicormic re-sprouts are forming the canopy. **See Appendix A- Photo 5**

**Discussion and Conclusions:**

Up to 80% of the CRZ of this tree is covered by cement and the footprint of the house. The driveway and parking pad for the carport appears to have been reconstructed since the house was built in the mid 1940's. Because of these construction activities, grading and soil movement occurred. Roots were potentially damaged and the original grade of the soil around the tree was raised at least 12 inches. When soil depth is changed and soil is placed against the trunk of a tree, the stem can suffocate and begin to decay. Often times structural roots rot over many years due to the suffocation. Secondary or adventitious roots form to feed the tree but provide no structural support and make the tree prone to failure.



P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

RECEIVED  
MAR 17 2011  
City of Paso Robles  
Community Development Dept

A large branch was removed from the north side of the tree 10 or more years ago. It is located approximately 6 feet above ground. The original diameter of the branch was approximately 36 inches. The open wound that remains is approximately 18 inches x 24 inches. The wound is callusing over, however decay has begun to form. It is not likely that the wound will seal over before decay advances significantly into the stem of the tree. The main stem of the tree above the wound has a lean of approximately 30 degrees to the west and over the house. The length of the stem above the wound is approximately 45 feet. The weak area of the stem with the large wound and decay combined with the lean and height of the stem make the possibility of stem failure at the wound point somewhat likely.

This tree has been topped significantly in the past. By my estimation of the re-growth, the work occurred in the last 10 years. Most of the lateral branches were removed leaving only 3 main scaffolds and some stubbed secondary branches. As a response to topping, epicormic shoots or "suckers" have re-grown from the topping points. Epicormic shoots originate from beneath the surface of the bark and are typically weakly attached to the parent branches. As these shoots gain height and diameter, they tend to fail during wind events.

I used the ISA Tree Risk Assessment Form to determine the risk rating for each part of the tree. The rating for the roots was moderate, the risk rating for failure of the stem was also moderate. The risk rating for branch failure was low. No mitigations short of full removal can be done to lower risk of root or stem failure. Removal of the epicormic shoots from the canopy would temporarily remove the risk of small branch failure; however that action would further stress the tree.

This tree is in very close proximity to the home and should not have been retained when the house was constructed. No doubt the tree was smaller in the 1940's but because of its potential mature size it was a poor choice to keep in the location. In an effort to live with the tree in the tight location, the owners of the tree have had it pruned significantly. The tree has been reduced to no more than a stem with a few branches covered with re-sprout growth. The tree has outgrown its space and now has structural issues that make it prone to failure at the roots, stem and canopy. I believe the risk in keeping this tree outweighs the benefits the tree provides.

**Recommendation:** I recommend full removal of this tree.

Sincerely,

Rodney D. Thurman  
ISA Certified Arborist PN 2684AUM  
ISA Tree Risk Assessment Qualification

Appendices: Photographs, ISA Tree Risk Assessment Form



**Whit's-Turn  
Tree Care**


P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

RECEIVED


FEB 15 2017

City of Paso Robles  
Community Development Dept.

## Appendix A- Photos



**Photo 1-** Full view of tree from street and southeast side of home




**Whit's-Turn**  
Tree Care

P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

RECEIVED

MAR 15 2017

City of Pasa Robles  
Community Development Dept



**Photo 2-** View of paved and restricted CRZ highlighted in yellow hash marks. House footprint also contributes to restricted root-space.



**Whit's-Turn  
Tree Care**

P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

RECEIVED

MAR 31 2017

City of Paso Robles  
Community Development Dept



**Photo3-** Close-up of grade buried root crown and restricted root space.



P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

REGISTRATION

MAR 13 2017

City of Plano Facilities  
Community Development Dept



**Photo 4-** Close-up of large wound on north side of tree. Arrow indicates formation of decay.



**Whit's-Turn  
Tree Care**

P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

FILED  
MAY 1 2017  
City of Los Angeles  
Community Development Dept




Photo 5- Epicormic shoots growing from topping points.



Whit's-Turn  
Tree Care  
P.O. Box 1784 Templeton, CA 93465  
Telephone: 805-434-9630 Fax: 805-434-9610

City of Templeton  
Community Development Dept

Appendix B- Forms

### ISA Basic Tree Risk Assessment Form

Client: Linda Thornbyck Date: 2/13/2017 Time: 9:00 am  
 Address / Tree location: 3162 1st Street, Paso Robles, CA Tree no.: \_\_\_\_\_ Sheet 1 of 1  
 Tree species: Valley Oak - Quercus lobata dbh: 10" Height: 50' Crown spread d.a.: 40'  
 Assessor(s): Paul & Theresa Time frame: \_\_\_\_\_ Tools used: Sounding Mallet

**Target Assessment**

| Target number | Target description | Significance                        |                                     |                            | Frequency | Practical to remove target? | Beneficial practice? |
|---------------|--------------------|-------------------------------------|-------------------------------------|----------------------------|-----------|-----------------------------|----------------------|
|               |                    | Target within 10' of line           | Target within 15' of line           | Target within 1.5' of line |           |                             |                      |
| 1             | Issue              | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                            | 3         | no                          | no                   |
| 2             | driveway           | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                            | 3         | no                          | no                   |
| 3             | sidewalks          | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                            | 2         | no                          | no                   |
| 4             | people             | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |                            |           |                             |                      |

**Site Factors**

History of failures: none noted Topography: Flat  Slope: \_\_\_\_\_ % Aspect: \_\_\_\_\_  
 Site changes: None  Gravel  Site clearing  Chemical soil hydrology  Root cuts  Describe root crown buried - due to soil movement: \_\_\_\_\_  
 Soil conditions: Limited volume  Saline soil  Site low  Compacted  Paved  Over roots  50 % Describe pavement: driveway  
 Prevailing wind direction: NW Common weather: Strong winds  Ice  Snow  Heavy rain  Describe winter storms: \_\_\_\_\_

**Tree Health and Species Profile**

Vigor: Low  Normal  High  Foliage: None (seasonal)  None (leafed)  Normal  Chlorotic  Necrotic  Abiotic   
 Species failure profile: Branches  Trunk  Roots  Describe large branches: fork which extends beyond route for due to root rot

**Load Factors**

Wind exposure: Protected  Partial  Full  Wind tunneling  Relative crown size: Small  Medium  Large   
 Crown density: Sparse  Normal  Dense  Interior branches: Few  Normal  Dense  Vines/Mistletoe/Moss   
 Hardest or planned change in load factor: none noted

**Tree Defects and Conditions Affecting the Likelihood of Failure**

**— Crown and Branches —**

Unbalanced crown  ICH: \_\_\_\_\_'  Crack:  lightning damage:   
 Root w/dge/branches  Overall Max dia: \_\_\_\_\_'  Under rot  Included bark   
 Knots/Hangers: Number \_\_\_\_\_ Max dia: \_\_\_\_\_'  Weak attachments  Girdling/Neck hole  Sider   
 Over-extended branches  Previous branch failures  Similar branches present   
 Pruning history:  Thinned  Raised  Dead/missing bark  Cankers/Galls/Burls  Sawwood damage/decay   
 Reduced  Top led  Non-tailed  Cankers  Heartwood decay   
 Flash cuts   Response growth: \_\_\_\_\_

Main concern(s): failure of epicormic shoots

Load on defect: N/A  Minor  Moderate  Significant   
 Likelihood of failure: Improbable  Possible  Probable  Imminent

**— Trunk —**

Dead/missing bark  Abnormal bark texture/co      
 Cavity/rot/decay  Induced bark  Cracks   
 Sawwood damage/decay  Cankers/Galls/Burls  Sapwood   
 Lightning damage  Heartwood decay  Cankers/Moss   
 Cavity/rot/decay: \_\_\_\_\_' dia. Depth: \_\_\_\_\_'    
 Last 30'     
 Response growth:    
 Main concern(s): decay of single branch received direct sunlight

Load on defect: N/A  Minor  Moderate  Significant   
 Likelihood of failure: Improbable  Possible  Probable  Imminent

**— Roots and Root Collar —**

Color: buried (1) visible  Depth: 2' none  Stem girdling   
 Dead  Decay  Corky/decaying   
 Area:  Futility  Fungus   
 Cracks  Bark damaged/missing  Discoloration   
 Root rot/dieback  Soil weakness

Response growth: \_\_\_\_\_  
 Main concern(s): \_\_\_\_\_

Load on defect: N/A  Minor  Moderate  Significant   
 Likelihood of failure: Improbable  Possible  Probable  Imminent

Page 1 of 2

Page 1- ISA Basic Tree Risk Assessment Form

